

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION  
CERTIFICATE.**

No. 64/OPH/M.C/E-1

Date : 16/1/21

It is certified that an inspection team headed by Dr. A.K. Gupta,  
Chief Medical Officer, Project Hospital, URRVUNZ, Obra (Name of Officers  
with designation) from U.P. Raja Vidyalaya Ujjain Nigam Ltd. (Name of  
Department/Office) inspected the DAV Public School,  
Obra, Sonbhadra (U.P.) - 231219 (Name & Address of  
the School) on 16.1.2021 and found that the DAV Public School,  
Obra, Sonbhadra (U.P.) - 231219 (Name of school) has safe  
drinking water facilities for the students and members of staff of the institution and is maintaining  
the hygienic sanitation condition in the school building & the campus as per the norms  
prescribed by the Central/State/U.T Govt.

The above valid for a period of One year.

Signature with Seal : [Signature] 16/1/21

Name : Dr. A.K. Gupta

Designation : C.M.O

Chief Medical Officer  
Obra Project Hospital  
Obra-Sonbhadra

To

The Principal  
DAV Public School  
Obra - Sonbhadra (U.P.) PIN-231219

(Name & Address of the Institution)

PRINCIPAL  
D.A.V. PUBLIC SCHOOL  
OBRA THERMAL PROJECT  
OBRA, DISTT.-SONEBHADRA  
U.P., PIN-231219

[Signature]  
CHIEF MEDICAL OFFICER  
SONEBHADRA